GRAHAM + SIBBALD

Home Report

44 B Baron Taylor Street Inverness IV1 1QG

Date of Valuation: 30/08/2023 AIMS Ref: INV-2023\08\0135

single survey

survey report on:

Property address	44 B Baron Taylor Street
. ,	Inverness
	IV1 1QG

Customer	Girvans Properties

Prepared by	Graham + Sibbald LLP

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subjects comprise a first floor flat within a two storey terraced
	block with commercial premises below.

Accommodation	The accommodation can be summarised as follows:
	Ground Floor - Shared communal access security door, Vestibule, stairs and shared landing leading to
	First Floor - Private entrance door, Inner Hall, Kitchen/Living Room area with Bedroom off, Shower Room, Bedroom.

Gross internal floor area (m ²)	43

Neighbourhood and location	The subjects are situated within Inverness city centre fronting onto
	both Baron Taylor Street and Mealmarket Close. Immediate
	surrounding properties comprise dwellings of a mixed age and type
	and include a hot food premises at ground floor level. All main facilities
	and amenities can be found nearby.

44 B Baron Taylor Street Inverness IV1 1QG Inverness INV-2023\08\0135 Inspection Date:- 30/08/2023 First Inspection Date (if applicable):-

Age (year built)	Converted circa 2008

Weather	Dry.

Chimney stacks	None.

Roofing including roof space	The roof appears to be of mansard style comprising a flat profile metal section with pitched and slate clad areas.
	Given the nature of construction, there were no roof void areas available for inspection.
	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.

Rainwater fittings	The gutters and downpipes are of plastic manufacture.
	Visually inspected with the aid of binoculars where appropriate.

Main walls	The main outer walls are consistent with being of cavity block and stone construction and rendered externally with a wall thickness of approximately 400mm.
	Visually inspected with the aid of binoculars where appropriate. Foundations and concealed parts were not exposed or inspected.

Windows, external doors and joinery	The windows comprise timber frame, double glazed units. The private entrance door off the first floor shared landing is of timber construction.
	The external roofline fascias, eaves and soffits are all formed in timber.
	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.

External decorations	External decorations comprise painted finishes.
	Visually inspected.

Conservatories / porches	Not applicable.
--------------------------	-----------------

Communal areas	Access to the subjects is via a shared communal entrance door,
	hallway, stairs and first floor Landing.
	Circulation areas visually inspected.

Garages and permanent	Not applicable.
outbuildings	

Outside areas and boundaries	As far as we are aware, there are no outside areas or designated
	parking areas pertaining to the subjects.
	Visually inspected.

Ceilings	The ceilings are of plasterboard type.
	Visually inspected from floor level.

44 B Baron Taylor Street Inverness IV1 1QG Inverness INV-2023\08\0135 Inspection Date:- 30/08/2023 First Inspection Date (if applicable):-

Internal walls	Internal walls are of plasterboard type.
	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.

Floors including sub floors	The flooring is of suspended timber construction although we would emphasise that our inspection of floor surface areas was restricted due to the presence of fitted floor coverings and furnishings.
	Given the nature of construction with there being a property directly below, there were no sub-floor areas available for inspection. Surfaces of exposed floors were visually inspected. No carpets or
	floor coverings were lifted.

Internal joinery and kitchen fittings	The internal skirtings and architraves are of varnished timber finish, whilst internal doors are of timber construction.
	The Kitchen comprise a modern range of wall mounted cabinets and worktop surfaces with integrated appliances.
	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.

	Chimney breasts and fireplaces	None.
--	--------------------------------	-------

Internal decorations	Internal decorations comprise painted finishes.	
	Visually inspected.	

Cellars	Not applicable.
---------	-----------------

Electricity	Mains supply. The electrical installation comprises 13 amp power points and the cable where visible is of PVC clad type. The electrical consumer unit is contained within a cupboard at the entrance hall. The electrical meter is within a cupboard at the communal stairwell.
	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards.

Gas	Mains supply.
	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern
	standards.

Water, plumbing, bathroom fittings	Mains supply. The visible plumbing installation is in copper and plastic pipework where seen. The Shower Room comprises a modern three piece suite with there being a WC, wash hand basin and mixer shower in-tray.
	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards.
	It should be appreciated that concealed areas beneath and around baths and shower trays could not be inspected. Water spillage in these areas can result in dampness/decay and no comment can be made on inaccessible areas. Waterproof seals in sanitary areas should be checked and maintained on a regular basis.

L

Heating and hot water	Fixed central heating is provided by a gas fired `Mini C24` combination boiler which is located within a cupboard off the hall and this serves a series of water filled radiators. This also provides for domestic hot water on demand.
	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances.

Drainage	Main sewer.
	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.

Fire, smoke and burglar alarms	There appears to be a compliant smoke and heat alarm system within the property.
	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	New smoke alarm standards were introduced in Scotland in February 2022 and it is likely that some properties may require additional
	works to meet these standards. In instances where alarms are in
	place, no tests whatsoever have been carried out and we cannot confirm if the system complies with the most recent regulations. Any
	potential purchaser should satisfy themselves as to whether the
	current system meets with regulations or otherwise.

Additional limits to inspection	At the date of inspection, the property was furnished whilst the floors were covered.
	There was no access gained to any sub-floor areas.
	There was no access gained to any roof void areas, given the nature of construction.
	Not all windows and doors were tested during the course of our inspection.
	Our inspection of the roof structure was restricted due to the roof and positioning of the property.
	Only the subject flat and internal communal areas giving access to the flat were inspected.
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.
	The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.
	No inspection for Japanese Knotweed was carried out and unless otherwise stated for the purpose of this report, it is assumed that there is no Japanese Knotweed within the boundaries of the property or neighbouring properties.
	It should be appreciated that the Home Report inspection is a non- disruptive visual inspection of the property as at the date of inspection and that we are unable to inspect parts of the property which are concealed or covered by floor coverings or contents in place at that time. Once vacant, defects may be apparent that could not be detected during our survey. Changing weather conditions can also affect aspects of the property which would not be apparent at the time of inspection.



Sectional Diagram showing elements of a typical house

Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

2Coping stone3Chimney head4Flashing5Ridge ventilation6Ridge board7Slates/tiles8Valley guttering9Dormer projection10Dormer flashing11Dormer cheeks12Sarking13Roof felt14Trusses15Collar16Insulation17Parapet gutter18Eaves guttering19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window pointing26Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Foundations36Solum37Floor joists38Floorboards39Water tank	1	Chimney pots
3Chimney head4Flashing5Ridge ventilation6Ridge board7Slates/tiles8Valley guttering9Dormer projection10Dormer flashing11Dormer cheeks12Sarking13Roof felt14Trusses15Collar16Insulation17Parapet gutter18Eaves guttering19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Floor joists38Floorboards39Water tank	2	
4Flashing5Ridge ventilation6Ridge board7Slates/tiles8Valley guttering9Dormer projection10Dormer flashing11Dormer cheeks12Sarking13Roof felt14Trusses15Collar16Insulation17Parapet gutter18Eaves guttering19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window pointing26Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Floorjoists38Floorboards39Water tank	3	
5Ridge ventilation6Ridge board7Slates/tiles8Valley guttering9Dormer projection10Dormer flashing11Dormer cheeks12Sarking13Roof felt14Trusses15Collar16Insulation17Parapet gutter18Eaves guttering19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window pointing26Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Floorboards38Floorboards39Water tank	4	Flashing
6Ridge board7Slates/tiles8Valley guttering9Dormer projection10Dormer flashing11Dormer cheeks12Sarking13Roof felt14Trusses15Collar16Insulation17Parapet gutter18Eaves guttering19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window pointing26Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Floor joists38Floorboards39Water tank	5	Ridge ventilation
7Slates/tiles8Valley guttering9Dormer projection10Dormer flashing11Dormer cheeks12Sarking13Roof felt14Trusses15Collar16Insulation17Parapet gutter18Eaves guttering19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window pointing26Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Foundations36Solum37Floor joists38Floorboards39Water tank	6	Ridge board
9Dormer projection10Dormer flashing11Dormer cheeks12Sarking13Roof felt14Trusses15Collar16Insulation17Parapet gutter18Eaves guttering19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window pointing26Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Foundations36Solum37Floor joists38Floorboards39Water tank	7	Slates/tiles
10Dormer flashing11Dormer cheeks12Sarking13Roof felt14Trusses15Collar16Insulation17Parapet gutter18Eaves guttering19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window pointing26Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Foundations36Solum37Floor joists38Floorboards39Water tank	8	Valley guttering
11Dormer cheeks12Sarking13Roof felt14Trusses15Collar16Insulation17Parapet gutter18Eaves guttering19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window pointing26Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Foundations36Solum37Floor joists38Floorboards39Water tank	9	Dormer projection
12Sarking13Roof felt14Trusses15Collar16Insulation17Parapet gutter18Eaves guttering19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window pointing26Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Foundations36Solum37Floor joists38Floorboards39Water tank	10	Dormer flashing
13Roof felt14Trusses15Collar16Insulation17Parapet gutter18Eaves guttering19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window pointing26Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Foundations36Solum37Floor joists38Floorboards39Water tank	11	Dormer cheeks
14Trusses15Collar16Insulation17Parapet gutter18Eaves guttering19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window pointing26Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Foundations36Solum37Floor joists38Floorboards39Water tank	12	Sarking
15Collar16Insulation17Parapet gutter18Eaves guttering19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window pointing26Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Foundations36Solum37Floor joists38Floorboards39Water tank	13	Roof felt
16Insulation17Parapet gutter18Eaves guttering19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window pointing26Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Foundations36Solum37Floor joists38Floorboards39Water tank	14	Trusses
 Parapet gutter Eaves guttering Rainwater downpipe Verge boards / skews Soffit boards Partition wall Lath / plaster Lath / plaster Chimney breast Window pointing Window sills Rendering Brickwork / pointing Bay window Lintels Cavity walls / wall ties Subfloor ventilator Damp proof course Base course Foundations Solum Floor joists Water tank 	15	Collar
18Eaves guttering19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window pointing26Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Foundations36Solum37Floor joists38Floorboards39Water tank		Insulation
19Rainwater downpipe20Verge boards / skews21Soffit boards22Partition wall23Lath / plaster24Chimney breast25Window pointing26Window sills27Rendering28Brickwork / pointing29Bay window30Lintels31Cavity walls / wall ties32Subfloor ventilator33Damp proof course34Base course35Foundations36Solum37Floor joists38Floorboards39Water tank	17	
 20 Verge boards / skews 21 Soffit boards 22 Partition wall 23 Lath / plaster 24 Chimney breast 25 Window pointing 26 Window sills 27 Rendering 28 Brickwork / pointing 29 Bay window 30 Lintels 31 Cavity walls / wall ties 32 Subfloor ventilator 33 Damp proof course 34 Base course 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 		e e
 21 Soffit boards 22 Partition wall 23 Lath / plaster 24 Chimney breast 25 Window pointing 26 Window sills 27 Rendering 28 Brickwork / pointing 29 Bay window 30 Lintels 31 Cavity walls / wall ties 32 Subfloor ventilator 33 Damp proof course 34 Base course 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 	19	
 22 Partition wall 23 Lath / plaster 24 Chimney breast 25 Window pointing 26 Window sills 27 Rendering 28 Brickwork / pointing 29 Bay window 30 Lintels 31 Cavity walls / wall ties 32 Subfloor ventilator 33 Damp proof course 34 Base course 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 		e e e e e e e e e e e e e e e e e e e
 23 Lath / plaster 24 Chimney breast 25 Window pointing 26 Window sills 27 Rendering 28 Brickwork / pointing 29 Bay window 30 Lintels 31 Cavity walls / wall ties 32 Subfloor ventilator 33 Damp proof course 34 Base course 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 		
 24 Chimney breast 25 Window pointing 26 Window sills 27 Rendering 28 Brickwork / pointing 29 Bay window 30 Lintels 31 Cavity walls / wall ties 32 Subfloor ventilator 33 Damp proof course 34 Base course 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 		
 25 Window pointing 26 Window sills 27 Rendering 28 Brickwork / pointing 29 Bay window 30 Lintels 31 Cavity walls / wall ties 32 Subfloor ventilator 33 Damp proof course 34 Base course 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 		
 26 Window sills 27 Rendering 28 Brickwork / pointing 29 Bay window 30 Lintels 31 Cavity walls / wall ties 32 Subfloor ventilator 33 Damp proof course 34 Base course 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 		
 27 Rendering 28 Brickwork / pointing 29 Bay window 30 Lintels 31 Cavity walls / wall ties 32 Subfloor ventilator 33 Damp proof course 34 Base course 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 		
 28 Brickwork / pointing 29 Bay window 30 Lintels 31 Cavity walls / wall ties 32 Subfloor ventilator 33 Damp proof course 34 Base course 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 	26	
 29 Bay window 30 Lintels 31 Cavity walls / wall ties 32 Subfloor ventilator 33 Damp proof course 34 Base course 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 	27	e e e e e e e e e e e e e e e e e e e
 30 Lintels 31 Cavity walls / wall ties 32 Subfloor ventilator 33 Damp proof course 34 Base course 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 		
 31 Cavity walls / wall ties 32 Subfloor ventilator 33 Damp proof course 34 Base course 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 		
 32 Subfloor ventilator 33 Damp proof course 34 Base course 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 		
 33 Damp proof course 34 Base course 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 		3
 34 Base course 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 		
 35 Foundations 36 Solum 37 Floor joists 38 Floorboards 39 Water tank 		
36 Solum37 Floor joists38 Floorboards39 Water tank		
37 Floor joists38 Floorboards39 Water tank		
38 Floorboards39 Water tank		
39 Water tank		-
/III 🔲 HOT WATER TANK		
	40	HOT WATER TANK

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with	Repairs or replacement	No immediate action or repair
them may cause problems to other parts of the property or cause	requiring future attention,	is needed.
a safety hazard. Estimates for repairs or replacement are needed	but estimates are still	
now.	advised.	

	Structur	tural movement		
Repair catego	bry	1		
Notes		At the time of our inspection there was no evidence of significant structural movement noted to affect the property within the limits of our inspection.		
	Dampne	ess, rot and infestation		
Repair catego	bry	1		
		There was no evidence found of significant dampness, rot or infestation within those areas of the property available for inspection.		
Chimney		/ stacks		
Repair catego	pry	N/A		
Notes		Not applicable.		
	Roofing	including roof space		
Repair catego	bry	1		

Notes	At the time of our visit to the property the roof generally appeared in fair order although there will be the requirement for ongoing maintenance and repairs. We would emphasise that our inspection of the roof coverings was greatly restricted.		
Repair category	1		
Notes	At the time of our inspection there was no evidence of damp staining/water staining on wall surfaces which would indicate leakage. It should be noted that it was not raining at the time of our inspection.		
Main wa	alls		
Repair category	2		
Notes	There was some evidence of localised damaged rendering and blockwork noted to the outer walls.		
Window	rs, external doors and joinery		
Repair category	1		
Notes	These generally appeared in fair condition consistent with age.		
	Windows can be problematic and over time the operation of the windows can be affected and opening mechanisms damaged. It is therefore likely that maintenance/ repair will be required as part of an ongoing maintenance programme.		
External	decorations		
Repair category	1		
Notes	The external decorations are generally in fair order although some weathering was noted Regular repainting will be required if these areas are to be maintained in satisfactory condition.		

44 B Baron Taylor Street Inverness IV1 1QG Inverness INV-2023\08\0135 Inspection Date:- 30/08/2023 First Inspection Date (if applicable):-

	Conservatories / porches			
Repair category		N/A		
Notes		Not applicable.		
Communal areas		nal areas		
Repair catego	bry	1		
Notes		The communal areas serving the property appear to be adequately maintained.		
	Garages	and permanent outbuildings		
Repair catego	bry	N/A		
Notes		Not applicable.		
Outside areas and boundaries		areas and boundaries		
Repair catego	bry	N/A		
Notes		Not applicable.		
Ceilings				
Repair catego	bry	1		
Notes		Within the limits of our inspection these generally appeared in fair condition consistent with age.		
	Internal	walls		
Repair category		1		
Notes		Within the limits of our inspection these generally appeared in fair condition consistent with age.		

Floors in	including sub-floors			
Repair category	1			
Notes	No significant defects noted within the limitations of the inspection.			
	No access to the sub-floor chamber was possible at the time of our visit to the property. Within the limitations of our inspection there was no indication to suggest significant defects in this area. It will, however be appreciated that the area was not inspected and therefore no guarantees can be provided in this regard.			
Internal	joinery and kitchen fittings			
Repair category	1			
Notes	The internal joinery is generally in keeping with the age and type of property.			
	The kitchen units are of a modern type.			
Chimne	y breasts and fireplaces			
Repair category	N/A			
Notes	Not applicable.			
Internal	decorations			
Repair category	1			
Notes	The property appears in fair decorative condition consistent with age.			
Cellars				
Repair category	N/A			
Notes	Not applicable.			

Electric	Electricity				
Repair category	1				
Notes	The electrical system within the property appeared of modern design, there being a circuit breaker type distribution board. It should be emphasised that the system was not tested at the time of our inspection. The Institution of Engineering and Technology recommends that inspections and testing are undertaken at least every ten years and on a change of occupancy. It should be appreciated that only the most recently constructed or re-wired properties will have installations which fully comply with IET regulations.				
Gas					
Repair category	1				
Notes	In the interest of safety all gas appliances should be checked by a Gas Safe Registered Engineer.				
Water,	plumbing and bathroom fittings				
Repair category	1				
Notes	The sanitary fittings are of modern style and type.				
	The plumbing and fittings appeared in serviceable condition but were not tested.				
Heating and hot water					
Repair category	1				
Notes	A gas fired central heating system has been installed. This will require ongoing and regular servicing.				
Drainage					
Repair category	1				

44 B Baron Taylor Street Inverness IV1 1QG Inverness INV-2023\08\0135 Inspection Date:- 30/08/2023 First Inspection Date (if applicable):-

Notes	There was no surface evidence to suggest the system is choked or leaking.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	N/A
Roofing including roof space	1
Rainwater fittings	1
Main walls	2
Windows, external doors and joinery	1
External decorations	1
Conservatories / porches	N/A
Communal areas	1
Garages and permanent outbuildings	N/A
Outside areas and boundaries	N/A
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	N/A
Internal decorations	1
Cellars	N/A
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for

repairs or replacement are

Category 3

Category 2

needed now.

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability,

value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property: In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres: For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1.	Which floor (s) is the living accommodation on?		First		
2.	Are there three steps or fewer to a main entrance to a property?	Yes		No	X
3.	Is there a lift to the main entrance door of the property?	Yes		No	X
4.	Are all door openings greater than 750mm?	Yes		No	X
5.	Is there a toilet on the same level as the living room and kitchen?	Yes	х	No	
6.	Is there a toilet on the same level as a bedroom?	Yes	х	No	
7.	Are all rooms on the same level with no internal steps or stairs?	Yes	х	No	
8.	Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes		No	Х

4. Valuation and conveyance issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

We are unaware of any adverse planning proposals affecting the subjects although this should be confirmed by obtaining a Property Enquiry Certificate.

Absolute Ownership assumed. We are unaware of any easements, servitudes or rights of way which may adversely affect the property. This point should be confirmed by reference to the Title Deeds.

The subjects form part of a block of flats and it has been assumed that maintenance/repair costs of the common parts of the building and external grounds will be shared on an equitable basis with the adjoining proprietors. It is therefore assumed that the costs of repairs detailed within this report which relate to these areas should be apportioned accordingly, although exact liability should be confirmed.

The property is located directly above a commercial hot food premises. This may have an impact upon future mortgageability.

Estimated reinstatement cost for insurance purposes

£140,000

The guidance figure is the estimate of costs for reinstating the subjects as at the date if inspection based on information provided by the Building Cost Information Service (BCIS). Building costs are currently increasing significantly above inflation due to increased demand and supply issues as a result of Brexit and the pandemic. It is recommended that this figure is kept under regular review to ensure that you have adequate insurance cover.

We are of the opinion that the subjects should be insured for buildings reinstatement purposes for a sum of not less than £140,000 (ONE HUNDRED AND FORTY THOUSAND POUNDS STERLING).

Valuation and market comments

£115,000

We are of the opinion that the market value of the subjects all as previously described and on a vacant possession basis would be fairly stated in the region of £115,000 (ONE HUNDRED AND FIFTEEN THOUSAND POUNDS STERLING).

Our valuation reflects current market conditions relating to this area. We would assume that current trends will prevail at the ultimate date of disposal with no adverse or onerous matters being introduced into the market during the intervening period which would have a detrimental effect on price.

44 B Baron Taylor Street Inverness IV1 1QG Inverness INV-2023\08\0135 Inspection Date:- 30/08/2023 First Inspection Date (if applicable):-

Report author	Neil Cromarty
Address	4 Ardross Street, Inverness. IV3 5NN.
Address	4 Aldioss Street, Inverness. IVS SNN.

Signed	Not and
	Neil Cromarty BAcc MRICS For and on behalf of Graham + Sibbald LLP

TERMS AND CONDITIONS OF SINGLE SURVEY

GENERAL

1.1 The Surveyors

The Seller has engaged the Surveyors to provide the Report and a Generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited energy company.

The Surveyors are authorised to provide a transcript or retype of the Generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by brokers and lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the Generic Mortgage Valuation Report and the Report. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the Generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancingprocess which materially affects the valuation stated in the Report and Generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors are required to amend the valuation in consequence of such information, they will issue an amended Report and Generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and Generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon residential property. *

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's agent or relative to the Property, they will be obliged to indicate this in the adjacent box. No

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

* Which shall be in accordance with the current RICS Appraisal and Valuation Standards (The Red Book) and RICS Rules of Conduct.

1.2 The Report

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to the 1st of December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Report is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Report may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective Purchasers and the Purchaser and their respective professional advisors without the prior written consent of the Surveyors.

1.3 Liability

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and is prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would be (or, as the case might be, would have been) disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisors of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

Graham + Sibbald's total liability to the Client (and any third party relying upon this report) under this Agreement (including liability in contract, tort (including negligence), breach of statutory duty, or otherwise) shall be limited to the lower of the following : a) 25% of the valuation or b) £250,000.

1.4 Generic Mortgage Valuation Report

The Surveyors undertake to the Seller that they will prepare a Generic Mortgage Valuation Report, which will be issued along with the Report. It is the responsibility of the Seller to ensure that the Generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 Transcript Mortgage Valuation for Lending Purposes

The Surveyors undertake that on being asked to do so by a prospective Purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. ** The Transcript Mortgage Valuation Report for Lending Purposes will be prepared from information contained in the Report and the Generic Mortgage Valuation Report.

** Which shall be in accordance with the current RICS Appraisal and Valuation Standards (The Red Book) and RICS Rules of Conduct.

1.6 Intellectual Property

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 Payment

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports, including replacement home reports.

1.8 Cancellation

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the Property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the Property, the Surveyor concludes that the Property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the following paragraph of this section.

In the case of cancellation by the Seller, for whatsoever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

If our account details change, we will notify these to you by letter or face to face and never by email.

1.9 Precedence

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 Definitions

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a Surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is the estimated amount for which the Property should exchange, on the date of valuation, between a willing seller and a willing buyer in an arms length transaction after proper marketing where the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in Part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property;
- the "Surveyors" are Graham + Slbbald LLP, a limited liability partnership incorporated in Scotland (Registered Number SO307130) and having its registered office address at Seabraes House, 18 Greenmarket, Dundee, DD1 4QB, of which the Surveyor is an employee, director or member (unless the Surveyor is not an employee, director or member, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report; and

44 B Baron Taylor Street Inverness IV1 1QG Inverness INV-2023\08\0135 Inspection Date:- 30/08/2023 First Inspection Date (if applicable):-

- the "Energy Report" is the advice given by the accredited energy company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.
- "Data Protection Legislation" means the UK Data Protection Legislation and any other European Union legislation relating to personal data and all other legislation and regulatory requirements in force from time to time which apply to a party relating to the use of personal data (including, without limitation, the privacy of electronic communications).
- "UK Data Protection Legislation" means all applicable data protection and privacy legislation in force from time to time in the UK including the UK GDPR; the Data Protection Act 2018; the Privacy and Electronic Communications Directive 2002/58/EC (as updated by Directive 2009/136/EC) and the Privacy and Electronic Communications Regulations 2003 (SI 2003/2426) as amended.
- "UK GDPR" has the meaning given to it in section 3(10) (as supplemented by section 205(4)) of the Data Protection Act 2018.

DESCRIPTION OF THE REPORT

2.1 The Service

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by statute and this is in the format of the accredited energy company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 The Inspection

The inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the Property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the Property.

The inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the Report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Report of Property that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a register of asbestos and effective management planis in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 The Report

The Report will be prepared by the Surveyor who carried out the Property inspection and will describe various aspects of the Property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the Property will be concise and will be restricted to matters that could have a materialaffect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the Property is free of any other minor defects.

Throughout the Report the following repair categories will be used to give an overall opinion of the state of repair and condition of the Property:

2.3.1 Category 3:

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the Property or cause a safety hazard. Estimates for repairs or replacement are needed now.

2.3.2 Category 2:

Repairs or replacement requiring future attention, but estimates are still advised.

2.3.3 Category 1:

No immediate action or repair is needed.

WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly developinto more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the Property. This is particularly true during slow market conditions when the effect can be considerable. Parts of the Property which cannot be seen or accessed will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 Services

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 Accessibility

A section is included to help identify the basic information interested parties need to know to decide whether to view a Property.

2.6 Energy Report

A section is included that makes provision for an Energy Report, relative to the Property. The Surveyor will collect physical data from the Property and provide such data in a format required by an accredited Eeergy company. The Surveyor cannot of course accept liability for any advice given by the energy company.

2.7 Valuation & Conveyancer Issues

The last section of the Report contains matters considered relevant to the conveyancer (solicitor). It also contains the Surveyor's opinion both of the market value of the Property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation within a willing buyer and willing seller in an arms-length transaction after proper marketing wherein the parties have each acted knowledgably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of uninspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions.
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees). Sellers or prospective Purchasers may consider it prudent to instruct a re-inspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

It is assumed that any relevant Local Authority consents, warrants and completion certificates have been obtained where construction or alteration works have been undertaken.

This agreement and any dispute or claim arising out of or in connection with its subject matter shall be governed by and construed in accordance with the laws of Scotland, and the Scottish Courts will have exclusive jurisdiction to hear such claims.

DATA PROTECTION

Graham + Sibbald and the Client each undertake that:

- (a) they shall comply with all applicable requirements of the Data Protection Legislation, including without limitation any obligations relating to the rights of a data subject and the reporting of personal data breaches (all as defined in the UK GDPR); and
- (b) not do or omit to do anything which puts any other party to the Agreement in breach of the Data Protection Legislation.

Without prejudice to the generality of this clause, you shall ensure that you have all necessary appropriate consents and notices in place to enable lawful transfer of the personal data to Graham + Sibbald for the duration and purposes of this Agreement. You shall have liability for and shall indemnify Graham + Sibbald for any loss, liability, costs (including legal costs), damages, or expenses resulting from any breach by you of the Data Protection Legislation. For further information regarding how Graham + Sibbald processes personal data in relation to this Agreement, please see Graham + Sibbald's privacy notice at https://www.g-s.co.uk/privacy-policy/.

	Mortgage V	aluation Report	for Home Repo	rtGR	AHAM
					BALD
Source: G+S Home Repo	rt	Seller Name Gin	rvans Properties	Reference II	NV-2023\08\0135
1) Property Details	House Name				
	Number / Ext 44	1 B			
	Street Ba	aron Taylor Street			
	Area				
	Town In	verness	Postcode IV1 1C	lG	
2) Description of proper					
Property Type	1	House Type Conv	verte d	Floor number of subject p	roperty 1
Year Built Converted cir	rca 2008	Non Traditional Co	nstruction? No	No. of floors	in block 2
		(*Specify under ger	neral comments)	No. of flats	in block 2
3) Accommodation - give					
	edrooms 2	Kitchens 1			lo of floors 1
Other None.	Garage(s)	No	Outbuildings None.	Garden _{No}	ne.
4) Tenure Absolute Ow	vnership	If Leasehold, ye	ears unexpired:		
Any known or reported p	problems with oner	rous or unusual grou	nd rent or service ch	arges?	
	.				
Owner occupied	Tenanted	Vacant x			
If part tenanted, pleas give detai					
5) Subsidence, Settleme	ent and Landslip				
Does the property show subject to landslip, he					
If yes, please					
clarify					
6) Condition of Property		al repairs required?		Yes	No x
		al repairs required?		Yes	No x
Should the repairs be				Yes	No
		tion recommended?		Yes	No x
' If the answer to any of t			de further detail:		
					RICS
		F	Page 1 of 3		Regulated by RICS
					Chartered Surveyors A Quality Assured Firm

I

7) Services Mains water x Mains drainage x Electricity x Gas x Central heating	Gas
8) Insurance Reinstatement Value Total area of all floors measured internally (m²)	43
Cost of rebuilding inc. demolition, site clearance, professional fees, local authority requirements and main building (inc all other structures within the site boundaries unless specifically excluded	£140,000
9) Market Valuation for Mortgage Purposes (Assuming Vacant Possession) Comment on mortgageability	
The subjects are situated directly above a commercial hot food premises and this may have an imp mortgageability, although in our opinion, the property does form suitable security for loan purpose lenders criteria which may yary	
Valuation in present condition:	£115,000
Valuation on completion of any works required under Question 6:	
10) General Comments Please advise of any special features of the property and/or the location, which affects the proper	ty.
The subjects comprise a first floor flat within a two storey terraced block with commercial premise walls are consistent with being of cavity block and stone construction and rendered externally with approximately 400mm. The roof is of mansard style comprising a flat profile metal section with pi The subjects are situated within Inverness city centre fronting onto both Baron Taylor Street and M	h a wall thickness of tched and slate clad areas.
Immediate surrounding properties comprise dwellings of a mixed age and type and include a hot floor level. All main facilities and amenities can be found nearby.	
At the date of inspection, the property was found to be in generally fair order consistent with age a being no immediate repairs recommended as a condition of mortgage.	and type and with there
We are unaware of any adverse planning proposals affecting the subjects although this should be Property Enquiry Certificate.	confirmed by obtaining a
Absolute Ownership assumed. We are unaware of any easements, servitudes or rights of way whi property. This point should be confirmed by reference to the Title Deeds.	ch may adversely affect the
The subjects form part of a block of flats and it has been assumed that maintenance/repair costs of building and external grounds will be shared on an equitable basis with the adjoining proprietors that the costs of repairs detailed within this report which relate to these areas should be apportion exact liability should be confirmed.	s. It is therefore assumed
L IMPORTANT - THIS IS A CONFIDENTIAL REPORT PREPARED FOR MORTGAGE PURPOSES.	
Certificate: I have personally inspected the property described herein and confirm adequate profesheld.	ssional indemnity cover is
Company / Firm Name Gra	
Signature Null Signature Office Addr1 4 A	
Office Addr2	
Valuer name and Neil Cromarty BAcc MRICS Area	
qualification For and on behalf of Graham + Sibbald LLP Town Inv	/erness
Date of inspection 30/08/2023 Postcode IV	
Date of report 04/10/2023 Tel no 01/	463 236977
Page 2 of 3	

MORTGAGE VALUATION - CONDITIONS OF ENGAGEMENT



In these Terms and Conditions of Engagement, the following expressions shall have the following meanings:

"Agreement" means these Terms and Conditions of Engagement, the Instructions and the confirmation letter issued by Graham + Sibbald.

"Client"/"you"/"your" means the person, firm, company, organisation or other entity engaging Graham + Sibbald to provide the inspection services.

"Data Protection Legislation" means the UK Data Protection Legislation and any other European Union legislation relating to personal data and all other legislation and regulatory requirements in force from time to time which apply to a party relating to the use of personal data (including, without limitation, the privacy of electronic communications).

"Graham + Sibbald"/"we"/"us"/"our" means Graham + Sibbald LLP, a limited liability partnership incorporated in Scotland (Registered Number SO307130) and having its registered office address at Seabraes House, 18 Greenmarket, Dundee, DD1 4QB.

"Instructions" means the written or verbal instructions by the Client to Graham + Sibbald, which appoint Graham + Sibbald to provide the inspection services.

"Property" means the property identified and described in the Instructions.

"UK Data Protection Legislation" means all applicable data protection and privacy legislation in force from time to time in the UK including the UK GDPR; the Data Protection Act 2018; the Privacy and Electronic Communications Directive 2002/58/EC (as updated by Directive 2009/136/EC) and the Privacy and Electronic Communications Regulations 2003 (SI 2003/2426) as amended.

"UK GDPR" has the meaning given to it in section 3(10) (as supplemented by section 205(4)) of the Data Protection Act 2018.

A valuation for mortgage is a limited inspection and report produced for building societies, banks and other lenders to enable them to make a lending decision. IT IS NOT A SURVEY. Unless otherwise stated the date of valuation will be the date of inspection.

This report is used to guide the lender on the market value of the Property for mortgage purposes and is carried out for this purpose alone. Although the inspection will be carried out by a valuer who will usually be a qualified surveyor it is not a detailed inspection of the Property, and only major visible defects will be noted. Subject to reasonable accessibility, the roof space is inspected only to the extent visible from the access hatch without entering it. The surveyor will not inspect under floor areas, communal roof space or other parts not readily accessible. The exterior and roof of the Property will be inspected from ground level only from within the boundaries of the site and adjacent/communal public areas. The area of the Property will be taken into account, and the rooms individually inspected, but floor coverings and furniture will not advise as to whether these comply with regulations in respect of these services.

The surveyor may recommend that a part of the mortgage be retained by the lenders until such time as particular repair works are carried out. Similarly, the report may suggest that the borrower should undertake to carry out certain repairs or commission more extensive investigation where hidden defects are suspected since these may have a material effect on the value of the Property. If a retention is recommended then the figure should not be regarded as an estimate of repair costs. Its purpose is to protect the interests of the lending institution. It is recommended that detailed estimates be obtained before proceeding with the purchase. Attention is drawn to the fact that if a subsequent transcription of this report is prepared on a lenders form, then in order to comply with the lenders specific requirements, the wording or phraseology may differ. Many people rely on the mortgage valuation certificate in the mistaken belief that it is a detailed survey. The report is often made available to house buyers by lenders, but this does not mean that it should be relied upon as a report on the condition of the building.

The definition of 'market value' is the estimated amount for which a Property should exchange on the date of valuation, between a willing buyer and a willing seller in an arms-length transaction after proper marketing wherein the parties had acted knowledgeably, prudently and without compulsion. For the purpose of this market value the surveyor has assumed that vacant possession will be provided. Unless otherwise stated the surveyor has valued the interest on a comparable basis.

The inspection that has been undertaken should not be regarded as a survey. The surveyor did not inspect parts of the Property which were covered, unexposed or inaccessible and are therefore unable to report that any such part of the Property is free from defect. Defects which are not considered materially to affect the value of the Property or other matters which would be attended to during maintenance, may not have been mentioned. If defects have been mentioned in this report, they should be regarded as indicative and not exhaustive. For the purposes of this valuation the surveyor assumes that all uninspected areas are free from defect which would have a material effect on value.

In accordance with our normal practice, we must state that this report is for the use only of the party to whom it is addressed or their named client and no responsibility is accepted to any third party for the whole or any part of its content.

In addition, we would bring to your attention that neither the whole nor any part of this report, nor any reference thereto, may be included in any document, circular or statement without prior written approval of the form and context in which it will appear.

The surveyor shall, unless otherwise expressly agreed, rely upon information provided by the Client and/or the Client's legal or other professional advisers relating to tenure, leases and all other relevant matters.

For the purposes of this valuation the surveyor has assumed that all ground burdens are nominal or have been redeemed and that there are no unusual outgoings or onerous restrictions contained within the titles of which we have no knowledge. The surveyor has further assumed that the subjects are unaffected by any adverse planning proposals.

Unless otherwise stated, it is assumed that all the required valid planning permissions and statutory approvals for the building and for their use, including any recent or significant extensions or alterations, have been obtained and complied with. It has been further assumed that no deleterious or hazardous materials or techniques have been used in the construction of the subject and that there is no contamination in or from the ground or from the immediate surrounds.

The surveyor will not carry out an asbestos inspection and will not be acting as an asbestos inspector in completing a valuation inspection of Property that may fall within the Control of Asbestos Regulations 2012. No enquiry of the duty holder, as defined in the Control of Asbestos Regulations 2012, of the existence of an asbestos register, or of any plan for the management of asbestos will be made. Your legal adviser/conveyancer should confirm the duty holder under these regulations, the availability of an asbestos register and the existence and management of any asbestos containing materials. For the purposes of this valuation, the surveyor has assumed that there is a duty holder, as defined in the Control of Asbestos Regulations 2006, and that a register of asbestos and effective management plan is in place which does not require any immediate expenditure or pose a significant risk to health or breach the HSE Regulations.

The surveyor confirms that this mortgage valuation is prepared in accordance with the RICS Valuation - Global Standards 2017 and incorporating IVSC International Valuation Standards and, unless other stated, we are External Valuares a defined therein. Further information may also be obtained from the Royal Institution of Chartered Surveyors in Scotland, 10 Charlotte Square, Edinburgh EH2 40R.

As part of this remit, the surveyor may, where he/she feels qualified and experienced to do so, provide general comment on standard appropriate supplementary documentation, presented to us by the Client's lender and conveyancer. In the event of a significant amount of documentation being provided to us, an additional fee may be incurred. Any additional fees will be agreed with you in advance.

We confirm that Graham + Sibbald operates formal procedures to deal with complaints from clients in accordance with By-law 19, Regulation 2.7 of the Royal Institution of Chartered Surveyors Rules of Conduct and Disciplinary Procedures. A copy of this procedure is available on request.

Graham + Sibbald's total liability to the Client (and any third party relying upon this report) under this Agreement (including liability in contract, tort (including negligence), breach of statutory duty, or otherwise) shall be limited to the lower of the following: a) 25% of the valuation or b) £250,000.

This agreement and any dispute or claim arising out of or in connection with its subject matter shall be governed by and construed in accordance with the laws of Scotland, and the Scottish courts will have exclusive jurisdiction to hear such claims.

Graham + Sibbald and the Client each undertake that: (a) they shall comply with all applicable requirements of the Data Protection Legislation, including without limitation any obligations relating to the rights of a data subject and the reporting of personal data breaches (all as defined in the UK GDPR); and (b) not do or omit to do anything which puts any other party to the Agreement in breach of the Data Protection Legislation.

Without prejudice to the generality of this clause, you shall ensure that you have all necessary appropriate consents and notices in place to enable lawful transfer of the personal data to Graham + Sibbald for the duration and purposes of this Agreement. You shall have liability for and shall indemnify Graham + Sibbald for any loss, liability, costs (including legal costs), damages, or expenses resulting from any breach by you of the Data Protection Legislation. For further information regarding how Graham + Sibbald's privacy notice at https://www.g-s.co.uk/privacy-policy/.

Energy Performance Certificate (EPC)

Scotland

Dwellings

FLAT 2, 44B BARON TAYLOR STREET, INVERNESS, IV1 1QG

Dwelling type:	Top-floor flat
Date of assessment:	30 August 2023
Date of certificate:	03 October 2023
Total floor area:	43 m ²
Primary Energy Indicator:	178 kWh/m ² /year

Reference number: Type of assessment: Approved Organisation: Main heating and fuel:


7207-1019-7208-1837-9204 RdSAP, existing dwelling Elmhurst Boiler and radiators, mains gas

You can use this document to:

· Compare current ratings of properties to see which are more energy efficient and environmentally friendly

Estimated energy costs for your home for 3 years*

^t based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



Current Potential Very environmentally friendly - lower CO₂ emissions (92 plus) A B (81-91) 80 80 (69-80) C (55-68) D) E (39-54 (21-38) F (1-20) G Not environmentally friendly - higher CO₂ emissions

Energy Efficiency Rating

£2,358

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band C (77)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band C (80)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

There are currently no improvement measures recommended for your home.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282. THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

FLAT 2, 44B BARON TAYLOR STREET, INVERNESS, IV1 1QG 03 October 2023 RRN: 7207-1019-7208-1837-9204

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Cavity wall, as built, insulated (assumed)	****	*****
Roof	Flat, insulated (assumed)	★★★ ☆	★★★★☆
Floor	(other premises below) To external air, insulated (assumed)		_
Windows	Fully double glazed	★★★ ☆	★★★★ ☆
Main heating	Boiler and radiators, mains gas	★★★ ☆	★★★★ ☆
Main heating controls	Programmer, room thermostat and TRVs	★★★ ☆	★★★★ ☆
Secondary heating	None	—	_
Hot water	From main system	★★★ ☆	★★★★☆
Lighting	Low energy lighting in all fixed outlets	****	*****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 31 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 1.3 tonnes of carbon dioxide every year. You could reduce emissions by switching to renewable energy sources.

FLAT 2, 44B BARON TAYLOR STREET, INVERNESS, IV1 1QG 03 October 2023 RRN: 7207-1019-7208-1837-9204

Estimated energy c	osts for this home		
	Current energy costs	Potential energy costs	Potential future savings
Heating	£1,614 over 3 years	£1,614 over 3 years	
Hot water	£498 over 3 years	£498 over 3 years	Net and Parking
Lighting	£246 over 3 years	£246 over 3 years	Not applicable
Totals	£2,358	£2,358	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

None

FLAT 2, 44B BARON TAYLOR STREET, INVERNESS, IV1 1QG 03 October 2023 RRN: 7207-1019-7208-1837-9204

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	3,288	N/A	N/A	N/A
Water heating (kWh per year)	1,432			

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Assessor membership number: Company name/trading name: Address:	Mr. Neil Cromarty EES/009427 Graham & Sibbald 4 Ardross Street Inverness IV3 5NN
Phone number:	01463 236977
Email address:	inverness@g-s.co.uk
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Property address	
	44b Baron Taylor Street
	Inverness
	IV1 1QG

Seller(s)	Mrs Fiona Girvan
	Girvans Properties
	2-4 Stephens Brae
	Inverness
	IV2 3JN

Completion date of property questionnaire	04/10/2023
---	------------

GRAHAM - SIBBALD

Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1.	Length of ownership	
	How long have you owned the property? 2006	
2.	Council tax	
	Which Council Tax band is your property in? B	
3.	Parking	
	What are the arrangements for parking at your property? (Please tick all that apply)	
	• Garage	
	Allocated parking space	
	• Driveway	
	Shared parking	
	On street	
	Resident permit	
	Metered parking	
	Other (please specify): no parking	9
4.	Conservation area	
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	Νο

5.	Listed buildings	
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	Νο
6.	Alterations/additions/extensions	
a.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	
	If you have answered yes, please describe below the changes which you have made:	Yes
	Various alterations	
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.	Yes
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	Yes
	If you have answered yes, please answer the three questions below:	
	(i) Were the replacements the same shape and type as the ones you replaced?	Νο
	(ii) Did this work involve any changes to the window or door openings?	Yes
	(iii) Please describe the changes made to the windows doors, or approximate dates when the work was completed):	patio doors (with
	2007/2008 roughly	
	Please give any guarantees which you received for this work to y agent.	your solicitor or estate

7.	Central heating	
a.	Is there a central heating system in your property?	
	(Note: a partial central heating system is one which does not heat all the main rooms of the property $-\!\!\!$	Yes
	the main living room, the bedroom(s), the hall and the bathroom).	
	If you have answered yes or partial – what kind of central heating is there?	
	(Examples: gas-fired, solid fuel, electric storage heating, gas warm air).	
	gas central heating	
	If you have answered yes, please answer the three questions below:	
	(i) When was your central heating system or partial central heating2007/2008	g system installed?
	(ii) Do you have a maintenance contract for the central heating system?	No
	If you have answered yes, please give details of the company with which you have a maintenance contract:	
	(iii) When was your maintenance agreement last renewed? (Please and year).	provide the month
8.	Energy Performance Certificate	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes
9.	Issues that may have affected your property	
a.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	Νο
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	
ь.	Are you aware of the existence of asbestos in your property?	No
b.	, , , , , , , , , , , , , , , , , , , ,	

. P	lease tick which	services are connected to your pr	operty and give details of	the supplie
	Services	Connected	Supplier	
	Gas or liquid petroleum gas	Yes		
	Water mains or private water supply	Yes		
	Electricity			
	Mains drainage	Yes		
	Telephone			
	Cable TV or satellite			
	Broadband			
•	Is there a septic tank system at your property? <u>If you have answered yes</u> , please answer the two questions below:		No	
	(iv) Do you have appropriate consents for the discharge from your septic tank?			
	If you have an	have a maintenance contract for <u>nswered yes</u> , please give details o ve a maintenance contract:		No

11.	Responsibilities for shared or common areas	
a.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?	Νο
	If you have answered yes, please give details:	
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?	Yes
	If you have answered yes, please give details:	
	Not sure	
с.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	Νο
d.	Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries?	Νο
	If you have answered yes, please give details:	
	There are none	
e.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	Νο
	If you have answered yes, please give details:	
f.	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.)	Νο
	If you have answered yes, please give details:	
12.	Charges associated with your property	
a.	Is there a factor or property manager for your property?	Νο
	If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	

Is there a common buildings insurance policy?	Νο	
If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?		
Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.		
Specialist works		
As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	Νο	
If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.		
As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	Νο	
If you have answered yes, please give details:		
If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?		
<u>If you have answered yes</u> , these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself <u>please write</u> <u>below who has these documents</u> and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.		
Guarantees are held by:		
	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges? Please give details of any other charges you have to upkeep of common areas or repair works, for exammaintenance or stair fund. Specialist works As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property. As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? If you have answered yes, please give details: If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work? If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.	

14.	Guarantees		
а.	Are there any guarantees or warranties for any of the following:		
(i)	Electrical work	No	
(ii)	Roofing	No	
(iii)	Central heating	No	
(iv)	National House Building Council (NHBC)	No	
(v)	Damp course	No	
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	No	
b.	<u>If you have answered 'yes'</u> or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):		
с.	Are there any outstanding claims under any of the guarantees listed above?		No
	If you have answered yes, please give de		
15.	Boundaries		
	So far as you are aware, has any boundary of your property been moved in the last 10 years?		No
	If you have answered yes, please give de	tails:	

16.	Notices that affect your property	
	In the past three years have you ever received a notice:	
a.	advising that the owner of a neighbouring property has made a planning application?	Νο
b.	that affects your property in some other way?	Νο
с.	that requires you to do any maintenance, repairs or improvements to your property?	Νο
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.	

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

І АССЕРТ	
Name:	Fiona Girvan

Date: 04/10/2023